SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 14.00G
06/27/2013

Updates from previous versions:
Bug Fixes:

1. A change was made in the MicroMag that affected the way alarm names are created. This change would have caused MCS-Connect to display incorrect names from SW version 14.00J or later. RESOLUTION- I changed the method used to get the alarm string in the MicroMag so the alarm strings are correct in the old SW and the new.
2. Changed all sensor names beginning with "485" to begin with "BMS" instead.
3. Added back in the test for old I/O boards to V14.

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com